



(6061-T6 ALUMINUM PLATE 3/16" MIN. THICKNESS)

FULL THICKNESS/CONTINUOUS

4 mangalah manananananan mangalah katalah katalah katalah katalah katalah katalah katalah katalah katalah kata

MANUFACTURE OF ARCOSA

SCALE: FULL DATE: 08/01/19

ECP/BAB PANEL PUNCTURE REPAIR

REPAIR 059 - ECP/BAB PANEL REPAIR

NOTES:

*) CALL MANUFACTURER FOR SIZES GREATER THAN 18" x 18".